

TOILET & SHOWER BLOCK RISK ASSESSMENT

Persons at risk - all users, volunteers & contractors

Significant Hazards	Control measures taken to reduce risk	Residual risk rating	What further action required?
Unauthorised access	Keypad entry system Only authorised users allowed on site	LOW	Groups to put unit name on their door
Slips, trips and falls	Walkways and social areas clear of built-in obstacles Non-slip flooring in bathrooms	LOW	Spills and trip hazards to be cleared away promptly Wet floor sign to be used Uneven paving to be reported as soon as possible
Fire	See separate fire risk assessment Fire alarm system installed with call points & sensors No smoking in buildings	LOW	Annual test of fire alarms by external specialists All users given fire safety sheet
Legionella	See separate legionella risk assessment All plumbing, taps and services appropriate for use and conform to relevant guidelines No cold water storage	MEDIUM	Periodical internal checks of water temperature Periodical bacterial check of water quality by external contractor

Electrical	All electrical equipment PAT tested every 4 years Visual checks ongoing Hard wire electrical testing carried out 5 yearly with appropriate remedial work as required	LOW	Any suspect equipment to be retired and inspected immediately
Chemical burns/ reactions/inhalation	Equipment appropriate for use No bleach to be used Chemicals stored away from children	MEDIUM	First Aid kits on hand Only use cleaning products provided Children must have adult supervision when cleaning